



Laser class 2 in acc. to IEC 60825-1

www.disto.com



SAP. No. 788 219




1x



2 sec.



→ permanent



Key Combinations



2 sec.



2 sec.



2 sec.

→ change units

Keylock ON

CLEAR
OFF



2 sec.



Keylock OFF




< 2 sec.



Quick Start

Leica DISTO™ D210



- 1 ON/DIST (on/measure)
- 2 Add
- 3 Subtract
- 4 Functions
- 5 Measuring reference
- 6 Clear/Off

- when it has to be right

Leica
Geosystems



1x → ON





2 sec. → OFF




1x



2 sec.



FUNC 1x



FUNC 3x



→ History (1-10)


+ 1 ... 10

- 10 ... 1


CLEAR OFF + **FUNC** 2 sec.

→ delete history


FUNC 5x



FUNC 2x



FUNC 4x



FUNC 6x

